

AutoManufacturerUpdate

Mike Albert Vehicle Fleet Management

this issue

Issue No. 16
August 23, 2010

*Keeping you
up-to-date with
important
purchasing
news.*

For a complete
breakdown of our
products and services,
visit
www.mikealbert.com.

Contact our order-inquiry
hotline with any questions
regarding your vehicle
orders at 1.800.886.5828,
prompt 0; or e-mail us at
orderstatus@mikealbert.com



- Key Upcoming Order Cut-Off Dates
- Ford Focus Production Timing
- Chrysler Plant Closures
- GM Plant Closures
- GM Crossover Recall



Manufacturer Production Information

Visit our Web site for a complete listing of manufacturer production information, including order cut-off dates, initial order dates, production start-up dates, and more. Click [here](#) to access our Manufacturer Production Information.

Key Upcoming Order Cut-Off Dates

Ford Sport Trac	8/27/2010
Nissan Cube	9/01/2010

Ford Focus Production Timing

As shown by the timing below, there is a three-month gap between the 2011MY and 2012MY Focus units, during which none will be released from the plant.

Key Dates:

8/20/10.....Final Orders Due for 2011MY
11/5/10.....MY Final Production
9/6/10.....12MY Order Bank Opens
12/9/10.....Begin Schedule 2012MY for System Fill
1/3/11.....2012MY Job #1
2/1/11.....OK to Buy

Chrysler Plant Closures

Plant	Vehicles Affected	Downweeks
Belvidere	Caliber, Compass and Patriot	8/23/10, 9/20/10

GM Plant Closures

Plant	Vehicles Affected	Downweeks
Oshawa #1	Camaro	9/13

Contact our order-inquiry hotline with any questions regarding your vehicle orders at 1.800.886.5828, prompt 0; or e-mail us at orderstatus@mikealbert.com

GM Crossover Recall

Summary:

General Motors is recalling certain model year 2009-2010 Chevrolet Traverse, Buick Enclave, GMC Acadia, and Saturn Outlook vehicles. The second row seat side trim shield restricts the upward rotation of the safety belt buckle when the seat back is returned to a seating position after being folded flat. If the buckle contacts the seat frame, additional effort is required to return the seat to a seating position. If sufficient force is applied, the buckle cover could be pushed down the strap, exposing and partially depressing the red release button.

Consequence:

The safety belt may not restrain the occupant as intended during a crash, increasing the risk of injury to the seat occupant.

Remedy:

Dealers will modify the second row seat side trim shields. If a safety belt buckle is damaged, dealers will replace it free of charge. The safety recall is expected to begin on or before August 31, 2010. Owners may contact Chevrolet at 1-800-630-2438, Buick at 1-866-608-8080, GMC at 1-866-996-9463, and Saturn at 1-800-972-8876, or at the owner center at www.gmownercenter.com.